

Inspection Photos

API#045-09210

Operator: Caerus

Inspection Number: 692400451

Inspection Date: 12/14/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northeast.

December 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Morgan API#045-09210



Photo#2:
View of Location along County storage area & access road to South.

December 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Morgan API#045-09210



Photo#3:
Soil stockpiles remaining on Location. Large pile is on reclaimed portion of site.

December 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Morgan API#045-09210