

# Final Reclamation and Stormwater Inspection

December 4, 2018

Operator: 8 NORTH LLC - 10575

Location ID: 321405

Inspection Document #: 674902293

Boulder County, CO

NESE Section 28 T1S R69W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: 8 NORTH LLC – 10575/1S69W28  
Location ID: 321405



**Photo 1.** Photo taken from the location, facing East. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, the majority of the site is covered in weedy, annual vegetation which includes but not limited to field bindweed and kochia, with little perennial grass cover establishment.



**Photo 2.** Photo taken from the facility, facing East. Subsidence was observed on location.

Inspection Photos  
Location Name: 8 NORTH LLC – 10575/1S69W28  
Location ID: 321405



**Photo 3.** Photo taken from the location, facing South. Erosion control waddles left on site are deteriorating.



**Photo 4.** Photo taken from the location, facing South. See comments from Photo 3.



## Inspection Photos

Location Name: 8 NORTH LLC – 10575/1S69W28

Location ID: 321405



**Photo 5.** Photo taken from the location , facing Southwest. Strands of previous fencing appear to be left on site.



**Photo 6.** Photo taken from the location , facing Southwest. Strands of previous fencing appear to be left on site.



## Inspection Photos

Location Name: 8 NORTH LLC – 10575/1S69W28

Location ID: 321405



**Photo 7.** Photo taken along the access road , facing South. See comments under Photo 1.



**Photo 8.** Photo taken along the access road , facing South. See comments under Photo 1.