

Final Reclamation and Stormwater Inspection

December 4, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 321356

Inspection Document #: 674902299

Boulder County, CO

SWNE Section 12 T1S R69W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/1S69W12

Location ID: 321356



Photo 1. Photo taken from the well location looking towards the facility, facing East. Appears the Operator has removed all equipment but has not performed any reclamation activities on the well location itself.



Photo 2. Photo taken from the well location, facing North. Note the subsidence at the location.