

Lantz # SG 544-23
API# 05-045-21685
Inspection # 689702223



Lantz # SG 544-23
API# 05-045-21685
Inspection # 689702223



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Lantz # SG 544-23
API# 05-045-21685
Inspection # 689702223



Stained groud in front of separator (SG 333-23/SG 433-23)

Lantz # SG 544-23
API# 05-045-21685
Inspection # 689702223



Volumes have been written in on tank labels. The writing is small and faint.

Lantz # SG 544-23
API# 05-045-21685
Inspection # 689702223



Volumes have been written in on tank labels. The writing is small and faint.