

Inspection Photos

Operator: BP Production

API: 05-067-09576

Date: 11/29/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western project area from the southwestern corner edge facing northward.



Photo 4. View of Scotch thistles (*Onopordum acanthium*) within the southern project area.