



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Dec 4, 2018 10:23:50 AM MST
Server Receive Date:	Dec 4, 2018 10:24:34 AM MST
Reference Number:	20181204-1893211050
Location:	557 Airpark Dr, Durango, CO 81303, USA Dec 4, 2018 10:24:02 AM MST [View Map]

Information

Name	reclamationtablet
Date	Nov 21, 2018
Well Name	SNOOK GAS UNIT A 1
API Number	50670513900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Other Repaired Berm

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

cleaned out ditch of sediment and repaired berms.

Notes

treated weeds in the reclamation area.