

Inspection Photos

Location Name: FORK UNIT FEDERAL 3-4-2-1

Location ID: 05-103-08462

Inspection: 679702209



Photo 1. Location looking south



Photo 2. Gas leak at flange next to gas meter building.

