

Inspection Photos

Location Name: NORTH DOUGLAS CREEK 13-33-1-1

Location ID: 05-103-08435

Inspection: 679702211



Photo 1. Location looking southeast.



Photo 2. Uncapped or not LOTO raiser next to well head.