

Inspection Photo (s)
GGU Jolley 44C
API # 05-045-13772
Inspection # 689302655



Location Photo #1



Location Photo #2

Inspection Photo (s)
GGU Jolley 44C
API # 05-045-13772
Inspection # 689302655



**Location Photo #3, 2 Unmarked flow line riser
at separators.**



**Location Photo #4, Unmarked flow line riser
in tank battery.**

Inspection Photo (s)
GGU Jolley 44C
API # 05-045-13772
Inspection # 689302655



**Location Photo #5, Unmarked flow line riser
in tank battery.**