

Final Reclamation Inspection

December 14, 2018

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-31630

Inspection Document #: 682404266

Weld County, CO

SESW Section 16 T9N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE 16-9-66 #1H

API: 05-123-31630



Google Earth imagery taken October 14, 2017. Photo illustrates the well pad location (~4.3 acres) in relation to adjacent reference areas. Surface owner, State Land Board, communicated that it was satisfactory to leave the vegetation as is, even though the vegetation is not similar to reference areas.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Photo 1. Photo taken December 14, 2017 from the entrance of the location, facing North. Approach and gravel pile left behind which has not been reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Photo 2. Photo taken from the entrance of the location, facing East. Gravel has been removed from the entrance. However, does not appear the Operator seeded the approach area as there was no apparent germination of desirable plant species.

Inspection Photos
Location Name: STATE 16-9-66 #1H
API: 05-123-31630



Photo 3. Close-up photo taken from the approach area. Photo illustrates no desirable vegetative growth.



Photo 4. Photo taken December 14, 2017 from the southwest location, facing South. On December 14, 2018, rip-rap was still observed and was not removed.