

# Final Reclamation Inspection

December 14, 2018

Operator: ANADARKO E&P ONSHORE LLC - #2800

API: 05-123-33866

Inspection Document #: 682404273

Weld County, CO

NENW Section 5 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 1.** Photo taken from the well location AND battery location, facing Southeast. No equipment or debris observed. Appears the location has been returned to the surface owner for crop production. Operator shall continue to monitor and manage the Location until it meets Rule 1004 standards.

Inspection Photos

Location Name: CHRISTNER #8-66-5-3XH

API: 05-123-33866



**Photo 2.** Photo taken from the well location AND battery location, facing South.  
See comments under Photo 1.