

Inspection Photos

Location Name: NORTH DOUGLAS CREEK 4-12-2-2

Location ID: 05-103-07780

Inspection: 679702231



Photo 1. Location looking north.



Photo 2. Pit without permit on file.