

## Inspection Photos

Location Name: FORK UNIT 12-11-2-2

Location ID: 05-103-08081

Inspection: 679702235



**Photo 1. Location looking north.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: FORK UNIT 12-11-2-2**  
**Location ID: 05-103-08081**  
**Inspection: 679702235**



**Photo 2. Gas meter pit without permit on file.**



**Photo 3. Separator pit without permit on file.**