

Inspection Photos
Location Name: Ruebel ET A#1-3
Location ID: 320247



Photo 1 WH



Photo 2 WH stained soil removed

Inspection Photos
Location Name: Ruebel ET A#1-3
Location ID: 320247



Photo 3 TNK BTRY



Photo 4 Fence repaired

Inspection Photos
Location Name: Ruebel ET A#1-3
Location ID: 320247



Photo 5 Hole in fence



Photo 6 Reels in side of fence of location

Inspection Photos
Location Name: Ruebel ET A#1-3
Location ID: 320247



Photo 7 Reel outside of fence running down hill



Photo 8 Sediment down slope of location burring land owners fence.