

Final Reclamation and Stormwater Inspection

December 11, 2018

Operator: AXIS EXPLORATION LLC – 10646

Location ID: 320750

Inspection Document #: 674902323

Arapaho County, CO

SENE Section 16 T4S R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: AXIS EXPLORATION LLC – 10646/4S64W16

Location ID: 320750



Photo 1. Photo taken west of the well location looking towards the facility, facing East. Appears the Operator has performed reclamation activities on the well location, part of the access road and the facility. Note the equipment left on site to left on the above photo.



Photo 2. Photo taken from the access road, facing West. See comment from Photo 1.

Inspection Photos

Location Name: AXIS EXPLORATION LLC – 10646/4S64W16

Location ID: 320750



Photo 3. Photo taken at the facility location, facing East. See comments from Photo 1.



Photo 4. Photo taken at the facility location, facing North. Photo depicts pipe still in ground on location.