

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)

Inspection Date: 11/29/2018




Photo # - 1

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 2

North side of tank battery view southeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 3

South side of tank battery view east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 4

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 5

Oil skim tank view southwest



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 6

South side of production pit berm containing oily material



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 7

Accumulation of oil on the south side of the eastern production pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 8

Accumulation of oil on the south side of the eastern production pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 9

Oily soil in the southern production pit berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 10

Oily soil in the southern production pit berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 11

Oily soil in the southern production pit berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 12

Oily soil in the southern production pit berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Impetro Resources LLC – Bosley 1 Location (313910)
Inspection Date: 11/29/2018



Photo # - 13

Oily soil at the Bosley 1 wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources