

Final Reclamation and Stormwater Inspection

December 12, 2018

Operator: PDC ENERGY INC – 69175

Location ID: 327807

Inspection Document #: 674902326

Weld County, CO

SENE Section 25 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327807



Photo 1. Photo taken from the access road looking towards the location, facing East. Appears the Operator has not performed any reclamation activities on the well location or access road.



Photo 2. Photo taken from the facility location, facing South. Appears the Operator has left equipment on locaiton.

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327807



Photo 3. Photo taken from the access road, facing Southeast. See comments from Photo 1.



Photo 4. Photo taken within location, facing East. See comments from Photo 2.

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327807



Photo 5. Photo taken within location, facing East. See comments from Photo 2.



Photo 6. Photo taken within location, facing West. See comments from Photo 1.