

Inspection Photo (s)
Shideler 32-3D
API # 05-045-08062
Inspection # 689302691



Location Photo #1



Location Photo #2

Inspection Photo (s)
Shideler 32-3D
API # 05-045-08062
Inspection # 689302691



Location Photo #3



**Location Photo #4, No secondary berm
around tank**

Inspection Photo (s)
Shideler 32-3D
API # 05-045-08062
Inspection # 689302691



Location Photo #5