

Inspection Photos

Operator: BP Production

API: 05-067-09019

Date: 11/29/2018



Photo 1. View of stormwater controls installed within the southwestern project area, appears to be functioning at this time.



Photo 2. View of diversion along the western project area from the southwestern corner facing northward.