

Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018



Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018



Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018



Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018



Gas venting through ball valve.



Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018



Dec 17, 2018 16:01:16
38.39864N 105.12897W
Fremont County



Location Name: Lobach #1 API: 043-40034 Inspection Date: 12/17/2018

