

Inspection Photos

Location Name: Federal North Wildhorse 7-28 Location ID 323292

Inspection Date: 12/18/2018



Photo 1 – Federal North Wildhorse 7-28 Tank Battery Sign



Photo 2 – Federal North Wildhorse 7-28 Pit from northwest corner



Inspection Photos

Location Name: Federal North Wildhorse 7-28 Location ID 323292

Inspection Date: 12/18/2018



Photo 3 – Federal North Wildhorse 7-28 Tank Battery.



Photo 4 – Leaky fitting at Federal North Wildhorse 7-28 wellhead. Operator contacted via phone to repair gas leak.

