

Inspection Photos
Location Name: Federal Falcon 33-6 Location ID 331150
Inspection Date: 12/18/2018



Photo 1 – Federal Falcon 33-6 tank battery



Photo 2 – Federal Falcon 33-6 tank battery, secondary containment requires maintenance



Inspection Photos
Location Name: Federal Falcon 33-6 Location ID 331150
Inspection Date: 12/18/2018



Photo 3 – Federal Falcon 33-6 skim tank



Photo 4 – Federal Falcon 33-6 produced water pit

