

## Inspection Photos

Location Name: Federal Macaw 33-1 Location ID 330960

Inspection Date: 12/18/2018



Photo 1 – Federal Macaw 33-1 Tank Battery and Sign



Photo 2 – Skim tank adjacent produced water pit at Federal Macaw 33-1



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Federal Macaw 33-1 Location ID 330960

Inspection Date: 12/18/2018



**Photo 3 – Produced water pit. Pit is dry with accumulated weeds.**



**Photo 4 – East side of Macaw 33-1 produced water pit showing gap in netting coverage.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources