

**Inspection Date: 12/18/2018**



**Photo 2 – Treater Door Ajar at Hoffman 34-10**

## Inspection Photos

Location Name: Hoffman 34-7,34-10 Pit and Production Facility Location ID 409486

Inspection Date: 12/18/2018



**Photo 3 – Heater Treat and produced water tanks, Hoffman 34-10**



**Photo 4 – Former produced water pits, Hoffman 34-7,34-10**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources