

Inspection Photos
Location Name: Elliot 6-27 Location ID 318847
Inspection Date: 12/18/2018



Photo 1 – Looking west toward subsidence along probably pipe toward former pit



Photo 2 – Probable former produced water pit at approximately Lat: 40.634386 Lon: -103.851922.



Inspection Photos
Location Name: Elliot 6-27 Location ID 318847
Inspection Date: 12/18/2018



Photo 3 – Former pit in foreground looking uphill toward former tank battery.



Photo 4 – Oily waste present in former production/tank battery area.



Inspection Photos
Location Name: Elliot 6-27 Location ID 318847
Inspection Date: 12/18/2018



December 18, 2018 12:07

Photo 5 – Overview of former production area looking west.



December 18, 2018 12:07

Photo 6 – Former Elliot 6-27 wellpad.



Inspection Photos
Location Name: Elliot 6-27 Location ID 318847
Inspection Date: 12/18/2018



Photo 7 – Overview of former production area looking north

