

Inspection Photos

Operator: BP Production

API: 05-067-06685

Date: 11/30/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing southward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*) and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western project area from the southwestern corner facing northward.