

Inspection Photos

Location Name: Howard-66N64W /27NENW

Location #: 326883



Photo #1

Howard 3-27 (API # 05-123-13811) wellsite

Shut-In

No well sign or Emergency Contact number posted.
from prev FIR



Photo #2

Howard 3-27 wellsite

Well sign & Emergency contact number now posted



Inspection Photos

Location Name: Howard-66N64W /27NENW

Location #: 326883



Photo #1
Howard 3-27 Battery
H2O vault
No contents or capacity posted.
from prev FIR



Photo #2
Howard 3-27 Battery
H2O vault
Contents & Capacity now posted.
No NFPA Placard



Inspection Photos

Location Name: Howard-66N64W /27NENW

Location #: 326883



Photo #3

Howard 3-27 Battery

from prev FIR

