

Inspection Photos

API#045-06774

Operator: Black Hills

Inspection Number: 692400455

Inspection Date: 12/17/2018





Photo#1:
Overview of Location from access road entry to East.

December 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Fee 10-1 API#045-06774



Photo#2:
Overview of Location to West.

December 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Fee 10-1 API#045-06774



Photo#3:
Cheat grass, Redstem filaree and Kochia are well established.

December 17, 2018



Photo#4:
Cheat grass, Redstem filaree and Kochia are well established.



Photo#5:

One pile of Debris was noted at NW side of Location, area also infested with Kochia.

December 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Fee 10-1 API#045-06774