

Inspection Photos
Location Name: Mesa E1-797
Location ID: #441653
Inspection Date: December 18, 2018



Photo #1 – View of excavated spoils stockpile from south side.



Photo #2 – View of excavated spoils stockpile from east.

Inspection Photos
Location Name: Mesa E1-797
Location ID: #441653
Inspection Date: December 18, 2018



Photo #3 – View to SE of pad, looking toward open excavation area.



Photo #4 – Operator was conducting interim reclamation operations on inspection date.