

Inspection Photos
Location Name: HUSKY HILL 6-6
Location ID: 05-103-07997
Inspection: 679702302



Photo 1. Location looking northwest.



Photo 2. Barrel stored on location without secondary containment.