

Laramie Energy LLC
Api # 05-077-08690
Inspection # 675001572



Photo taken from entrance

Laramie Energy LLC
Api # 05-077-08690
Inspection # 675001572



No tank battery sign at entrance, well head or at tank battery

**Laramie Energy LLC
Api # 05-077-08690
Inspection # 675001572**



No wellhead sign



No well head sign

Laramie Energy LLC
Api # 05-077-08690
Inspection # 675001572



Weeds on location



Weeds on location

Laramie Energy LLC
Api # 05-077-08690
Inspection # 675001572



Sign on meter run. Not in compliance