

**SG 414-27**  
**API# 05-045-21001**  
**Inspection # 689702284**



**2" riser between wells along fence line.**

**SG 414-27**  
**API# 05-045-21001**  
**Inspection # 689702284**



**Unused 2" riser at wells**

**SG 414-27**  
**API# 05-045-21001**  
**Inspection # 689702284**



**Location Photo**