

**REPO A-10-34D**  
**API# 05-045-12614**  
**Inspection # 689702286**



**Location well heads photo**

REPO A-10-34D  
API# 05-045-12614  
Inspection # 689702286



Capacity numbers are faded.