

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2018

Submitted Date:

12/17/2018

Document Number:

689702225

FIELD INSPECTION FORM

Loc ID 334096 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|---------------------------------------|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Hartman, Robert | (970) 244-3041 | bhartman@blm.gov | Petroleum Engineer |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 270906 | WELL | PR | 06/16/2004 | GW | 045-09802 | S.PARACHUTE FEDERAL 25-32 | PR |
| 274833 | WELL | PR | 09/01/2018 | GW | 045-13419 | FEDERAL 25-13 (P25) | PR |
| 274834 | WELL | PR | 09/04/2014 | GW | 045-13418 | FEDERAL 25-12 (PK25) | PR |
| 275378 | WELL | PR | 09/01/2018 | GW | 045-13528 | FEDERAL 25-10(PK25) | PR |
| 291854 | WELL | PR | 12/15/2007 | GW | 045-14541 | FEDERAL 25-6BB (PK25) | PR |
| 291855 | WELL | PR | 01/08/2008 | GW | 045-14540 | FEDERAL 25-12BB (PK25) | PR |
| 291856 | WELL | PR | 12/31/2007 | GW | 045-14539 | FEDERAL 25-15BB (PK25) | PR |
| 291857 | WELL | PR | 09/01/2018 | GW | 045-14538 | FEDERAL 25-10BB (PK25) | WK |
| 291858 | WELL | PR | 09/01/2018 | GW | 045-14537 | FEDERAL 25-13BB (PK25) | PR |
| 291859 | WELL | PR | 12/20/2007 | GW | 045-14536 | FEDERAL 25-11 (PK25) | PR |

General Comment:

Routine FIU General Field Inspection

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | The phone number for local emergency services (911 where available) and the public road used to access the site is not posted on battery sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 02/17/2019 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 500 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 270906 | Type: | WELL | API Number: | 045-09802 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 274833 | Type: | WELL | API Number: | 045-13419 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 274834 | Type: | WELL | API Number: | 045-13418 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 275378 | Type: | WELL | API Number: | 045-13528 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291854 | Type: | WELL | API Number: | 045-14541 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291855 | Type: | WELL | API Number: | 045-14540 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291856 | Type: | WELL | API Number: | 045-14539 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291857 | Type: | WELL | API Number: | 045-14538 | Status: | PR | Insp. Status: | WK |
| Workover | | | | | | | | | |
| Comment: | RMWS swabbing well | | | | | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 291858 | Type: WELL | API Number: 045-14537 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

| | |
|-------------------------|-------|
| Comment: Producing well | |
| Corrective Action: | Date: |

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 291859 | Type: WELL | API Number: 045-14536 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing Well

| | |
|-------------------------|-------|
| Comment: Producing well | |
| Corrective Action: | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel | Pass | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| | | Gravel | Pass | | | |
| | | Compaction | Pass | | | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 401878053 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4680193 |
| 689702226 | Inspection 689702225 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4680190 |