

Final Reclamation Inspection

December 24, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-12701

Inspection Document #: 682404305

Weld County, CO

SESE Section 12 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



Google Earth aerial imagery from 6/16/2005 illustrating the disturbance areas associated with the location.

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



The most current Google Earth aerial imagery from 9/7/2013 illustrating the disturbance areas associated with the location during active operations. Bare patch is observed along the southwestern disturbance area. COGCC Staff will re-inspect this area on a future follow-up inspection to ensure compliance with Rule 1004 standards.

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



Photo 1. Photo taken from the eastern area of the former plugged and abandoned location, facing North. Well was plugged on 6/1/2015. Operator has failed to perform final reclamation activities (decompact, contour, remove gravel, etc.) per Rule 1004 standards.

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



Photo 2. Photo taken from the former plugged and abandoned location. Photo illustrates gravel has not been removed and decompaction has not been performed. COGCC Staff could not penetrate the shovel more than a couple inches into the surface.



Photo 3. Photo taken from the eastern area of the former plugged and abandoned location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SLW #2-12
API: 05-123-12701



Photo 4. Photo taken from the western area of the former plugged and abandoned location, facing Northwest. See comments under Photo 1.



Photo 5. Photo taken from the western area of the former plugged and abandoned location, facing East. See comments under Photo 1.