

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Methanol system | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|----------------------|-------------|
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: _____ |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | | corrective date |
|---------------------------|-----------------|-------|-----------------|
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Methanol system | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Facility #443867 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

| Berms | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Venting: | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Flaring: | | | | |
|--------------------|--|--|--|-------|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 248368 Type: WELL API Number: 123-16166 Status: PR Insp. Status: SI

Producing Well

Comment: SIBP

Corrective Action:

Date:

BradenHead

Comment: Bradenhead valve is exposed at surface.

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | Self Inspection | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 674301281 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687575 |