

Caerus Piceance LLC
Api # 05-077-08984
Inspection # 675001596



Photo of tank battery signs at separator units

Caerus Piceance LLC
Api # 05-077-08984
Inspection # 675001596



Photo from E side of location