

Inspection Photos

Operator: Logos Operating

API: 05-067-07455

Date: 12/18/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



12.18.2018

Photo 4. View of cobble run-down within the western project area.