

Final Reclamation and Stormwater Inspection

December 21, 2018

Operator: PELICAN HILL OIL & GAS INC – 10088

Location ID: 321956

Inspection Document #: 674902358

Cheyenne County, CO

NESW Section 21 T14S R46W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/14S46W21

Location ID: 321956



Photo 1. Photo taken from the location, facing North. Appears the Operator has performed final reclamation activities. However, several locations throughout the site lack uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to kochia.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/14S46W21

Location ID: 321956



Photo 3. Photo taken from the location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. See comments from Photo 1 and note the debris left on site.

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/14S46W21

Location ID: 321956



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/14S46W21

Location ID: 321956



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.