

Final Reclamation and Stormwater Inspection

December 21, 2018

Operator: PELICAN HILL OIL & GAS INC – 10088

Location ID: 381289

Inspection Document #: 674902359

Cheyenne County, CO

SESW Section 24 T15S R47W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/15S46W24

Location ID: 381289



Photo 1. Photo taken from the location, facing North. Appears the Operator has performed final reclamation activities. However, the majority of the site has not been decompacted.



Photo 2. Photo taken from the location, facing West. Photo depicts compaction areas to the right of the Photo and decompacted areas to the left. See comments from Photo 1.

Inspection Photos

Location Name: PELICAN HILL OIL & GAS INC – 10088/15S46W24

Location ID: 381289



Photo 3. Photo taken from the location showing the test pit dug to check on decompaction. See comments from Photo 1.



Photo 4. Photo taken from the location, facing North. Photo depicts compaction areas in the foreground of the Photo and decompacted areas in the background.