

Final Reclamation Inspection

December 24, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-18960

Inspection Document #: 682404307

Weld County, CO

NWNW Section 18 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



COGCC GISOnline aerial imagery from 2017. The main access road (highlighted in the red-dashed line) is no longer in need for oil and gas operations and historic imagery indicates this was not a pre-existing road. All associated wells and facilities have been plugged and abandoned along the main access road. Last well plugged along the main access road was 8/3/2015.



Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



Google Earth aerial imagery from 6/16/2005 illustrating some of the disturbance areas associated with the location during active operations, including a flowline. Operator shall comply with Rule 1004 standards to reclaim all associated disturbance areas.

Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



Photo 1. Photo taken from the northwestern main access road (shown in the first aerial image), facing East. Operator has failed to reclaim the access road per Rule 1004 standards (e.g., recontour, decompact, etc.). Wind erosion was observed along portions of the main access road.

Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



Photo 2. Photo taken from the entrance of the well location access road, facing South. Well was plugged on 3/4/2014. Operator has failed to properly reclaim the access road per Rule 1004 standards (e.g., recontour, decompact, etc.).

Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



Photo 3. Photo taken from the northern well location access road, facing South. See comments under Photo 1.



Photo 4. Photo taken from the southern well location access road, facing North. See comments under Photo 1.

Inspection Photos

Location Name: ROBIN GREEN STATE #BB 18-4

API: 05-123-18960



Photo 5. Photo taken from the approximate well location, facing West. Well location area is not reflective of reference area vegetation. Much of the well location is bare or has sparse vegetation establishment.



Photo 6. Reference photo taken west of the well location, facing West. See comments under Photo 4.