

# Inspection Photos

Operator: Logos Operating

API: 05-067-05592

Date: 12/18/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern project area from the northeastern corner facing westward.**



**Photo 3. View of cable debris within the northern project area, that needs to be removed.**