

Interim Reclamation and Stormwater Inspection

December 24, 2018

Operator: NOBLE ENERGY INC- #100322

Location ID: 330539

Inspection Document #: 682404331

Weld County, CO

NWSE Section 18 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SLW GREEN STATE #BB 18-10
Location ID: 330539



Photo 1. Photo taken of the Operator well sign. Well is currently shut-in.



Photo 2. Photo taken from the well location, facing North. Photo illustrates unmanaged weeds (Russian thistle) throughout the location. Russian thistle was observed well beyond the wellhead into interim reclamation areas and off location. Operator shall control weed debris per Rule 603.f. Also, Operator has failed to stabilize the production area. Wind erosion was observed.

Inspection Number: 682404331

Inspection Photos

Location Name: SLW GREEN STATE #BB 18-10

Location ID: 330539



Photo 3. Photo taken from the western well location, facing Southwest. See comments under Photo 2.



Photo 4. Photo taken from the southern well location, facing East. See comments under Photo 2.

Inspection Photos

Location Name: SLW GREEN STATE #BB 18-10

Location ID: 330539



Photo 5. Photo taken from the southeastern well location, facing Northeast. See comments under Photo 2.



Photo 6. Photo taken from the southeastern well location, facing North. See comments under Photo 2.