

Final Reclamation and Stormwater Inspection

December 21, 2018

Operator: WIEPKING-FULLERTON ENERGY LLC – 96340

Location ID: 381146

Inspection Document #: 674902361

Cheyenne County, CO

NENE Section 9 T14S R47W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: WIEPKING-FULLERTON ENERGY LLC – 96340/14S47W9

Location ID: 381146



Photo 1. Photo taken from the location, facing South. Appears the Operator has performed final reclamation activities. However, there is still debris left at the location.



Photo 2. Photo taken from the location. Note the half buried pipe left on site.

Inspection Photos

Location Name: WIEPKING-FULLERTON ENERGY LLC – 96340/14S47W9

Location ID: 381146



Photo 3. Photo taken from the location note the debris left on site.



Photo 4. Photo taken from the location note the debris left on site.