

Inspection Photos

Operator: BP America

API: 05-067-09002

Date: 12/18/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of the northern project area from the northeastern corner facing southward. Approximately 100 Russian knapweeds (*Rhaponticum repens*) growing on berm.