

Final Reclamation and Stormwater Inspection

December 20, 2018

Operator: PDC ENERGY INC – 69175

Location ID: 327636

Inspection Document #: 674902354

Weld County, CO

SWSE Section 25 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327636



Photo 1. Photo taken from the location, facing North. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, approximately half of the location and access road have no indication that compaction alleviation or reclamation was performed.



Photo 2. Photo taken from the facility, facing South. See comments under Photo 1.

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327636



Photo 3. Photo taken from the access road, facing South. Gravel remains along the access road and appears to have been seeded and straw crimped mulch over. See comments under Photo 1.



Photo 4. Photo taken from the access road. See comments from Photo 3.

Inspection Photos

Location Name: PDC ENERGY INC – 69175/1N67W25

Location ID: 327636



Photo 5. Photo taken from the access road, facing West. See comments under Photo 1.



Photo 6. Photo taken from the location, facing East. Appears equipment is left on site.