

Inspection Photos

Location Name: LEFT FORK P36-299

Location ID: 05-103-10689

Inspection: 679702374



Photo 1. Location looking northeast.



Photo 2. Container label not readable.



Inspection Photos

Location Name: LEFT FORK P36-299

Location ID: 05-103-10689

Inspection: 679702374




Photo 3. Tank capacity not readable.

