

**Inspection Photo (s)**  
**GMU 23-2C**  
**API # 05-045-10940**  
**Inspection # 689302807**



**Location Photo #1**



**Location Photo #2, Stained rock in battery containment.**