

**Inspection Photo (s)**  
**Benzel 26-15A**  
**API # 05-045-09069**  
**Inspection # 689302815**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Benzel 26-15A**  
**API # 05-045-09069**  
**Inspection # 689302815**



**Location Photo #3, Stained rock in battery containment.**