

Inspection Photos

Location Name: RGU 12-10-298D

Location ID: 05-103-10760

Inspection: 679702398



Photo 1. Location looking north.



Photo 2. Tank label volume capacity is illegible.

